

L Number	Hits	Search Text	DB	Time stamp
4	1754	(73/1.06,118.1,23.32).ccls.	USPAT	2004/08/13 08:19
5	36	(measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$) near7 (impedance or resistance or z) near20 positive near12 negative near12 polarit\$	USPAT	2004/08/13 08:34
6	61	(measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$ ((73/1.06,118.1,23.32).ccls.) and ((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$)	USPAT	2004/08/13 08:43
7	0	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$))	USPAT	2004/08/13 08:34
8	4617	(determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$)	USPAT	2004/08/13 08:42
9	0	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$))	USPAT	2004/08/13 08:37
10	0	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$)	EPO; JPO	2004/08/13 08:37
11	0	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$)	EPO; JPO	2004/08/13 08:38
12	61	(measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$)	USPAT	2004/08/13 08:39
13	15	(measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$)	EPO; JPO	2004/08/13 08:40
14	722	(determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$)	EPO; JPO	2004/08/13 08:40
15	0	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$))	EPO; JPO	2004/08/13 08:40
16	1464	(measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative	USPAT	2004/08/13 08:45

17		61	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative)	USPAT	2004/08/13 08:42
18		10124	(determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$)	USPAT	2004/08/13 08:43
19		11758	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$))	USPAT	2004/08/13 08:44
20		1	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$))	USPAT	2004/08/13 08:44
21		41	((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative) and (((73/1.06,118.1,23.32).cccls.) or ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$))) not (((measur\$ or determin\$ or comput\$ or detect\$ or calculat\$ or sens\$ or test\$ or monitor\$ or inspect\$) near10 (impedance\$ or impedance\$ or resistance or z) near25 positive near17 negative near12 polarit\$) and ((determin\$ or detect\$ or test\$ or check\$ or monitor\$) near7 (oxygen or (air near2 fuel)) near3 (sens\$ or detect\$)))	USPAT	2004/08/13 08:46